



Programming Failure - Chassis With Cummins Engine And An Allison Transmission



> **Internal Content**

It has been found that some units with a Cummins engine and an Allison transmission may be able to read parameters but unable to program parameters.

Advise to follow this procedure :

1. Remove the fuse for the Allison transmsion.
2. While disconnected from the truck, finish work in PTT and remove this vehicle from the " Latest Selections " list.
3. Connect to the truck's 16 pin diagnostic connector and read the vehicle data (minus the Allison and Cummins). Parameter programming should now function properly for chassis related programing with the Allison disconnected.
4. Reconnect the fuse and read/clear DTC's.



Tags

[cummins](#)

[allison](#)

[parameter programing](#)

Related links and attachments



Feedback

Live UI content available

[Give feedback](#)

to help improve the content of this article