

June 24, 2022

## Product Change Notice - ABS software and module install location change

Dear Valued Customer:

Please be advised, in response to customer feedback, Lippert intends to change the anti-lock braking system software to accommodate a new mounting location for the ABS control module.

- **Current system:** Module connectors are on the right side (Fig. 1) and module is mounted on the door side of the chassis.
- **Starting on or around June 27:** Module connectors will be on the left side (Fig. 2) and module must be mounted on the off-door side of the chassis.

There is no part number change and no price change.



Fig. 1- Current

Connectors



Fig. 2- New

If you have any questions, please feel free to call me directly or your LCI representative. We value and appreciate your business and partnership.

Sincerely,

**Briton Moffitt**

Product Manager

248.215.0487

[bmoffitt@lci1.com](mailto:bmoffitt@lci1.com)

## Frequently Asked Questions:

1. **Will a new part number be required?** No, there is no part number change.
2. **Does the price change for the item?** No, there is no price change.
3. **Is the new part wholly interchangeable with the previous version of the part?** Yes, however the replacement module will need to be configured by Lippert before it is shipped.
4. **Does the customer need to replace inventory?** No, the change will be made on a running basis, starting on or around June 27.