

9003812 11/01/2017 MY15 - 16 LA, LD, LX MY17 LD

GPOP - Issue Review System

Part Number: 05168389A\$, 68079723A\$

Part Description: Lower Control Arm

Issue Description: If replacing Lower Control Arm due to worn bushings, please note that replacement bushings are now available separate from the control arm.

~____~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system