

Driver's Side Door Weatherstrip is Distorted

AFFECTED VEHICLES

Year	Model	Trim Level
2022	Civic Sedan, Hatchback	ALL

Dealers and field staff have let us know about an issue with the driver's side door weatherstrip looking distorted. We wanted to let you know there is nothing wrong.

Now, rather than just leave you wondering why it's there, here's something interesting. The two nubs found on the weatherstrip was manufactured to channel the water away from the driver when the door is opened.

So, if a customer comes in with this question, or a PDI Tech is curious about it you have the answer.

