TECHNICAL TOPICS

Powertrain





Cl	lunk Noise from Front end with V8	22MY Range Rover Sport 22MY Defender
Customer Voice:		
-	Customer concern will be a clunk noise while driving at low speeds.	
Tec	chnical Description:	
_	This is currently under investigation and would like to direct you to TOPIX to assist you in this emerging concern.	
_	Follow TOPIx section 205-01 and 205-03 to diagnose the related concern. Checking all halfshafts , CV joints, bushings and differential mounting points.	
	Please raise a TA if you have this customer concern so we can have engineering look into these cases	
-	Upon completion of repairs, please raise an EPQR	









