


WMP6 Stop delivery - Replace valve springs



WMP6 Stop delivery - Replace valve springs

Update 3/29/22

Please be advised that repairs for WMP6 are currently available. The TI is now available in PCSS and the [AfterSales Document Database](#).

3 crucial parts for the campaign have been allocated to your dealer. These are:

- V04015001FR - Qty 16 per car
- V04015001FS - Qty 16 per car
- 9A710311301 - Qty 3 per car

All other parts will need to be ordered as normal with no PRMS ticket needed. Please use VOR when ordering. A VIN list with scope and parts list per scope is attached.

The Special tools needed are either available through your sister VW brand store, will be sent via Snap-On, or are available through the Porsche rental system. Rental instructions for dealers needing the rental kit will be sent via email. **If you receive the rental kit it is absolutely crucial that you send the kit to the next dealer when you are finished with it.**

WMP6 Stop delivery - Replace valve springs

These crucial special tools are:

- VAS 5161A
- VAS 5161A/38
- VAS 261 005

IMPORTANT REMINDER

Dealers should not deliver any vehicle affected by this notification prior to completing this action.

Overview

On the affected vehicles, the valve springs may have been manufactured out of specification. To help prevent potential valve spring breakage, the intake and exhaust side valve springs must be replaced.

Model type	Panamera (971) Cayenne (9YA/9YB)
Model year	2021-2022
Number of affected vehicles	72

Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain.

Any further use is not permitted. Test drives are to be omitted.

Test instructions and remedial measures

Are available in PCSS and the [AfterSales Document Database](#).