

10/7/15

MY15 JC Journey, RT minivan, VF Promaster

GPOP - Issue Review System

Part Number: 04800696A\$

Part Description: Flex Plate

Issue Description: If the part you are replacing is cracked; FCA would like to have the transmission replaced with the flexplate. Please call Jian Zhu on his cell (248) 379-1132.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
