

9/28/2016

MY17

KL

GPOP - Issue Review System

Part Number: 52014775A\$

Part Description: Condenser

Issue Description: For KL ONLY; Before replacing the Condenser for leaking, please call any of the following:~
Lan Sun @ cell (248) 736-8786
Shan Sundaram @ cell (248) 420-3643
If a response is not received within 15 minutes, proceed with the necessary repair.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.