

Fault Message In The Instrument Cluster About Rear Axle Steering

Topic number	LI46.80-P-075453
Version	1
Function group	46.80 - Auxiliary rear axle steering, auxiliary steering axle (ZL), electro-hydraulic auxiliary steering (EHZ)
Date	10/21/22
Validity	Model series 232 with M177 or M139
Reason for change	

Complaint

After engine start, the fault message "Rear axle steering not available" appears in the IC

Cause

Software

Remedy

New software available as of calendar week 41 / 2022

Flash affected control units with XENTRY.

Control unit N68/9 HAL-L (RAS232L)

Control unit N68/10 HAL-R (RAS 323R)

Symptoms	
Chassis/suspension > Steering system > Display message > Pow. steer. faulty Serviced Required	
Control unit/fault code	
Control unit	Fault text
N68/10 - Right rear axle steering (RAS232R) (RAS232R)	C11259A - The rear axle steering has a malfunction. The operating conditions for the component or the system are not satisfied.
	C1125F0 - The rear axle steering has a malfunction. Normalization of up/down steering column adjustment is missing.
	C112509 - The rear axle steering has a malfunction. There is a component fault.
N68/9 - Left rear axle steering (RAS232L) (RAS232L)	C11259A - The rear axle steering has a malfunction. The operating conditions for the component or the system are not satisfied.

XENTRY TIPS

	<p>C112509 - The rear axle steering has a malfunction. There is a component fault.</p> <p>C1125F0 - The rear axle steering has a malfunction. Normalization of up/down steering column adjustment is missing.</p>
--	---

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note