

Staining/surface damage on door trim strips and side window trim element

Topic number	LI72.00-P-075481
Version	1
Function group	72.00 - General
Date	10/24/22
Validity	MODEL 253
Reason for change	Item number for polishing agent updated

Complaint

Staining on door trim strips and top and bottom trim elements on rear side windows. See example pictures 1, 2 and 3.


Attachments	
File	Description
Bild 3.jpg	Example of door trim bar complaint on models with code P55/P60 (Night package)
	

Bild 2.jpg



Example of complaint relating to door upper trim strip in silver look

Bild 1.jpg



Overview of affected component parts

Cause

Damage to protective coating of door beltline trim strips, door upper trim strips and side window trim element due to strong alkaline detergent in car washes.

Remedy

1. Check if the complaint cannot be rectified by polishing the trim bars with the polish.
2. If the complaint cannot be rectified, replace the door beltline trim bars, door upper trim bars and rear side window with trim element with optimized protective coating.

WIS-References

Document number	Title	Note
AR67.30-P-2560LF	Install/remove triangular window	
AR72.10-P-1905LF	Remove/install sealing for crank window on front door	Operation steps 6, 7 and 8
AR72.12-P-1911LF	Remove/install seal for crank window on rear door	Operation steps 6, 7 and 8

XENTRY TIPS

Symptoms

Body > Door/Flap > Door > Trim > Surface damage

Parts

Part number	ES1	ES2	Designation	Quantity	Note	EPC
A2536702501			Left side window	1	Valid for MODEL 253.3	X
A2536702601			Right side window	1	Valid for MODEL 253.3	X
A2536702701			Left side window	1	Valid for MODEL with 253.3 with code 840	X
A2536702801			Right side window	1	Valid for MODEL with 253.3 with code 840	X
A2536702901			Left side window	1	Valid for MODEL 253.3 with code: ((P55/P60)+900)+-(807/808/809)	X
A2536703001			Right side window	1	Valid for MODEL 253.3 with code: ((P55/P60)+900)+-(807/808/809)	X
A2536703101			Left side window	1	Valid for MODEL 253.3 with code: ((P55/P60)+900)+-(807/808/809)	X
A2536703201			Right side window	1	Valid for MODEL 253.3 with code: ((P55/P60)+900)+-(807/808/809)	X
A2536703301			Left side window	1	Valid for MODEL 253.9	X
A2536703401			Right side window	1	Valid for MODEL 253.9	X
A2536703501			Left side window	1	Valid for MODEL with 253.9 with code 840	X
A2536703601			Right side window	1	Valid for MODEL with 253.9 with code 840	X
A2536703701			Left side window	1	Valid for MODEL 253.9 with code 840+(P55/P60)	X
A2536703801			Right side window	1	Valid for MODEL with 253.9 code 840+(P55/P60)	X
A2536703901			Left side window	1	Valid for MODEL with 253.9 code (P55/P60)	X
A2536704001			Right side window	1	Valid for MODEL with 253.9 code (P55/P60)	X
A2537207505			SEALING RAIL FOR LEFT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code 800/900	X
A2537207605			SEALING RAIL FOR RIGHT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code 800/900	X
A2537207705			SEALING RAIL FOR LEFT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code (P55+900/P60)	X
A2537207805			SEALING RAIL FOR RIGHT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code (P55+900/P60)	X
A2537255101			LEFT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.9	X
A2537255201			RIGHT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.9	X
A2537255301			LEFT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.9 with code (P55+900/P60)	X

XENTRY TIPS

A2537255401			RIGHT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.9 with code (P55+900/P60)	X
A2537255501			LEFT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.3	X
A2537255601			RIGHT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.3	X
A2537255901			LEFT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.3 with code (P55+900/P60)	X
A2537256001			RIGHT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.3 with code (P55+900/P60)	X
A2537308504			SEALING RAIL FOR LEFT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code 800/900	X
A2537308604			SEALING RAIL FOR RIGHT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code 800/900	X
A2537308704			SEALING RAIL FOR LEFT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code (P55+900/P60)	X
A2537308804			SEALING RAIL FOR RIGHT OUTER GLASS PANE	1	Valid for MODEL 253.3/9 with code (P55+900/P60)	X
A2537352901			LEFT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.9 with code 800/900	X
A2537353001			RIGHT TRIM BAR, ON GUIDE RAIL	1	Valid for MODEL 253.9 with code 800/900	X
A2537353101			TRIM BAR LEFT UPPER GUIDE RAIL	1	Valid for MODEL 253.9 with code (P55+900/P60)+-(806/807/808/809);	X
A2537353201			TRIM BAR RIGHT UPPER GUIDE RAIL	1	Valid for MODEL 253.9 with code (P55+900/P60)+-(806/807/808/809);	X
A2537353301			TRIM BAR LEFT UPPER GUIDE RAIL	1	Valid for MODEL 253.3	X
A2537353401			TRIM BAR RIGHT UPPER GUIDE RAIL	1	Valid for MODEL 253.3	X
A2537353501			TRIM BAR LEFT UPPER GUIDE RAIL	1	Valid for MODEL 253.3 with code: (P55/P60)+-(806/807/808/809);	X
A2537353601			TRIM BAR RIGHT UPPER GUIDE RAIL	1	Valid for MODEL 253.3 with code: (P55/P60)+-(806/807/808/809);	X
A0009864674	11		Polish	1		X

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
			67B1247	
			67P1247	
			72A4647	
			72N4647	
			73A4047	
			73N4047	
			72E0A47	
			72T0A47	

XENTRY TIPS

			73E0B47	
			73T0B47	