

Reference	SSM75864
Models	New Range Rover Sport / L461
Title	Rear Quarter Glass Finisher Abrasion Marks Below Tailgate Spoiler
Category	Body
Last modified	05-Oct-2022 00:00:00
Symptom	108000 Ext. Trim/Accessories
Attachments	SSM75864 Rear Quarter Glass Finisher Abrasion Marks Below Tailgate Spoiler Attachment1.pdf (SSM75864 Rear Quarter Glass Finisher Abrasion Marks Below Tailgate Spoiler Attachment1.pdf)
Content	<p>Issue: A customer may report that light scratches are visible on the outer rear quarter glass finisher when the tailgate is opened. Affecting L461 Range Rover Sport only.</p> <p>Cause: Rear spoiler winglet seals in contact with the glass finisher when the tailgate is in the closed position</p> <p>Action: Please carry out the following steps where damage is evident.</p> <ol style="list-style-type: none"> 1. Locate the spoiler winglet seals LH and RH (please view attachment step A). 2. Remove and discard the spoiler winglet LH and RH seal by peeling away the seal from the tailgate - Note: the seals can quite easily be removed by hand without the use of any hand tools. Step B shows the winglet seal following removal. 3. Remove and discard the decal tape from the finisher, if fitted (please view attachment step C). 4. Inspect the fixed glass finisher for signs of damage. 5. If no damage is found on the finisher, no further action is required. 6. If damage is detected carefully clean the finisher with a non-abrasive polish and return the vehicle to the customer. <p>Note: There is no need to replace the finisher as any abrasion marks can be removed using a suitable polish.</p>

anBhd#RlcmM7MjAyMj0xMj0wVVQxNzozMTYyNC4zMzJaOzEzNi4yMjYyNzluMTI3Ow==