Rear Storage Box Mod..pdf

Reference SSM66537

Models F-TYPE / X152

Title Rear Storage Box Door Opens When Locking Vehicle

Category Body

Last modified 24-Jun-2013 00:00:00

Symptom 107000 Interior Trim

Issue: The lockable rear interior storage box (cubby box) door may open when locking the vehicle doors. Cause: There are two separate causes depending on the VIN range. Vehicles built up to K00890 could have an issue with the storage box latch. Vehicles from K00890 to K03880 may be having the storage box lid preloaded by the left hand rubber stop for the storage box door.

Content

Action: For vehicles up to VIN K00890 please submit a Technical Assistance Request for further assistance. For vehicles from VIN K00890 to VIN K03880 remove the rubber stop on the left hand side of the rear storage box and cover the hole with suitable felt tape. See attached picture.