

BODY & CHASSIS

HVAC Control Module Software Update

23MY New Range Rover (L460),
23MY New Range Rover Sport (L461)

Customer Voice:

- A customer may report that the passenger compartment airflow temperature and distribution controls are unresponsive.

Technical Description:

- Revised HVAC module software has been developed to address this concern.

Status:

- SSM 75847 has been published for this concern.
- Service Action N749 is going through sign-off to proactively address this concern.

