

Reference	SSM75892
Models	Defender / L663
Title	L663 Noise From Sunroof Blind When Opening And Closing
Category	Body
Last modified	15-Nov-2022 00:00:00
Symptom	102000 Window/Glass
Content	<p>Issue: A customer may report that the sunroof blind appears to make a click type sound as it opens and closes.</p> <p>Cause: Currently under analysis with the JLR engineering team</p> <p>Action: If a customer reports the concern above or identified at Pre Delivery Inspection (PDI), please raise a Technical Assistance (TA) and attach a video clip with audio enabled recording the sound as the sunroof blind is opened and closed. The TA should be escalated to BES_305 – Glazing 7 Roofs quoting the SSM reference number.</p> <p>Please do not continue with diagnosis or attempt a repair until advised via the TA.</p> <p><small>anBhdHRicnM7MjAyMj0wNiQxNDozNzo1OC4wOTJhOzEzN4yMjYyNTUuMT11Ow==</small></p>