## WNN9 Workshop campaign - Recode central computer (PCM)

## WNN9 Workshop campaign - Recode central computer PCM

ID Number WNN9

Models Macan (95B)

Model Years 2022
VIN List Attached
Number of Affected VINs 9,291

Issue Description Due to potentially incorrect coding of the central com-

puter (PCM), it is possible that there will not be any traffic information (Real Time Traffic Information) displayed in the navigation system on the affected vehic-

les

To ensure this function on the affected vehicles, the central computer (PCM) must be re-coded using a

corrected data record.

What Dealers Should do Please arrange for this measure to be carried out as

soon as possible on affected vehicles. As of the time of this posting, the repair is immediately available.

TI Number No. 188-22

## Required software

PIWIS Tester 3 test software version 41.300.000 (or higher)

If other coding campaigns that affect the same control unit and involve the identical procedure are open for a vehicle in addition to this campaign, the affected control unit must only be coded once using the current PIWIS Tester test software.

Please proceed as follows for the campaigns that have not been carried out:

 Mark the campaign as 'cannot be carried out' with the reason "Modification of the affected component" in PQIS. The "Warranty relevance" flag must be activated in order to be able to set a warranty claim and close the campaign. • A warranty claim must be submitted for the campaign in which 0 time units is entered as the specified labor time and no material items are specified.

## Warranty processing

Validity:

This workshop campaign will be carried out up to September 15th, 2027 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code WNN9 66 000

Repair Code 1

Labor time 37 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.