

N749 UPS6922-1 – SOFTWARE UPDATES - HVAC MODULE



UPS CAMPAIGN - UPDATE PRIOR TO SALE N749 – HVAC MODULE UPDATE

AFFECTED MODELS	23MY New Range Rover and New Range Rover Sport
VOLUME AFFECTED	USA 1614
REPAIR	On certain 23MY New Range Rover and Range Rover Sport vehicles, there is a requirement to update HVAC module software to prevent the airflow temperature and distribution controls from becoming unresponsive.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	December 1st, 2022
Notes	Repairs are also being performed in ports of entry. There are 729 affected vehicles in retailer inventory. Please check the Warranty Portal or BBSS inventory reports for any affected VIN at your store and ensure these vehicles are updated prior to sale.