

## GPOP - Issue Review System

**Part Number:** 52014588A\$, 52014609A\$, 52014619A\$, 52014620A\$, 52014753A\$, 52014798A\$, 52014808A\$, 55057062A\$, 68197293A\$, 68229581A\$, 68232744A\$, 68258786A\$, 68268591A\$, 68268592A\$, 68268593A\$, 68312697A\$, 52014632A\$, 52014775A\$, 52014797A\$, 52014948A\$, 52014978A\$

**Part Description:** CONDENSER, Air Conditioning

**Issue Description:** CONDITION 1: If it is determined that the A/C compressor does not engage due to a refrigerant leak at the receiver/drier plug on the A/C condenser, order the receiver/drier plug kit P/N 68447796A\$ and follow the repair instructions included on the instruction sheet.~

~

CONDITION 2: For stock at the dealership of the below Part Number level or older ONLY, use kit 68447796A\$ to change the desiccant BAG and the desiccant bag access PLUG before installing the Cooler on the vehicle.~

52014588AD level and older only.~

52014609AC level and older only.~

52014632AC level and older only.~

52014797AG level and older only.~

52014948AE level and older only.~

52014978AF level and older only.

~

~  
Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.