

TECHNICAL BULLETIN 225



Notice Information

Ref	21765
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (US&CA) – June 21, 2022

TOL Ref. #21765-SVC

TECHNICAL BULLETIN 225

Triumph has released **Technical Bulletin 225** containing details for **Diagnostic Tool 2022-7**.

This complete bulletin, and all technical bulletins, can be found on TriumphOnline.net (TOL) [Technical Bulletin Page](#). Please print and ensure that all relevant staff in your dealership/market are familiar with the action.

PLEASE ENSURE ABSENT STAFF ARE INFORMED ON THEIR RETURN.

TECHNICAL BULLETIN 225 CONTENTS		
Item	Subject	Model Affected
225	Triumph Diagnostic Tool 2022-07 Update - ECM Status Report Feature - Beta A	Models fitted with an Engine ECM with three connectors
225	Triumph Diagnostic Tool 2022-07 Update - Introduction of New Headlight ECM Hardware	Tiger 1200 GT, Tiger 1200 GT Pro, Tiger 1200 GT Explorer, Tiger 1200 Rally, Tiger 1200 Rally Explorer
225	Triumph Diagnostic Tool 2022-07 Update - Calibrations Removed From Service	See Item 3

Reminder: Use the **“VIN Enquiry”** function within TOL (found under the **Service / Technical** drop-down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives, or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.

