

# PDI ADDITIONAL CHECKPOINT - SCREW-ON FLUID RESERVOIR CAPS



## Notice Information

Ref	21829
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor
Subject:	Service/Technical

**TOL NOTICE (US&CA) – June 29, 2022**


**TOL Ref. #21829-SVC**

## PDI ADDITIONAL CHECKPOINT - SCREW-ON FLUID RESERVOIR CAPS

In addition to checking the fluid level during the PDI for any motorcycle model fitted with screw-on type reservoir cap, also check that the cap is correctly tightened with all reservoir elements seated correctly.

An example reservoir shown below for reference.

Diagram Description automatically generated



802119

1. Reservoir cap
2. Plastic plate
3. Diaphragm seal
4. MAX mark
5. MIN mark

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.

