

# DIAGNOSTIC TOOL 2022-08



## Notice Information

Ref	22008
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

**TOL NOTICE (USCA) – July 20, 2022**

**TOL Ref. #22008-SVC**

## DIAGNOSTIC TOOL 2022-08

Triumph has released diagnostic software [version 2022-08](#). It is now available to download and update your workshop computer. Please download (from the Triumph Diagnostic Tool page under the Service/Technical menu on TOL) today and commence using immediately.

**This release addresses the following subjects with more information and model listing in the attached Release Notes.**

### **Engine ECM Calibrations**

Updated calibrations released for the following models:

- Tiger 1200 GT
- Tiger 1200 GT Pro
- Tiger 1200 GT Explorer
- Tiger 1200 Rally Pro
- Tiger 1200 Rally Explorer.

### **Instrument Calibrations**

Updated calibrations released for the following models:

- Trident 660
- Tiger Sport 660
- Tiger 900 Bond Edition.

### **Connectivity Module Calibrations**

New calibration released for all models that can be equipped with a Triumph Connectivity Module.

### **Reminder:**

- Please ensure all new bikes have the latest software download at PDI
- Please ensure the latest software is download on all bikes being serviced
- **PLEASE ENSURE ALL RELEVANT STAFF ARE INFORMED OF THIS UPDATE**

- (Remember to update those returning from holiday/absence)

The attached **TDT Release Notes 2022-08** are stored and available to download anytime from the dedicated TDT page within TOL.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.