

| | |
|----------------------|---|
| Reference | SSM71896 |
| Models | XK / X150 XJ / X351 XF / X250 |
| Title | Automatic transmission, rotary gear selector low level part |
| Category | Electrical |
| Last modified | 16-Jul-2014 00:00:00 |
| Symptom | 203000 Basic Electrical |
| Content | <p><u>ISSUE</u></p> <p>The complete Gear Shift Modules (GSM) are being replaced when there has been a claim reported of an appearance defect with the Rotary Gear Selector (rotary control knob) , with issues such as peeling chrome and rough edges.</p> <p>The Rotary Gear Selector can be replaced independently using a service kit</p> <p>Service kit C2D38186 is available for XK150 12MY onwards & XJ351 10MY onwards</p> <p>Service Kit C2Z8728 is available XK150 & XF250 pre 12MY</p> <p>Service Kit C2Z29872 is available on XF250 12MY onwards</p> <p><u>Cause</u></p> <p>Rotary control knob being replaced due to poor appearance</p> <p>Note: The Rotary control knob should only be replaced under warranty if the appearance is due to a manufacturing defect</p> <p><u>Action</u></p> <p>If the customer claims that there is a poor appearance of the rotary control knob it can be replaced using the Rotary Gear selector service kit.</p> <p>Removal procedure documented in the workshop manual section 307-05(A) Transmission control switch(TCS)knob</p> |