

Field campaign

Topic	Rear Seat Entertainment - Update (SC22/31)
Market area	Russische Föderation (5RU),Australia E04 Bentley rest Asia and Australia (6E04),Germany E02 Bentley rest Europe (6E02),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2068183/2
Campaign number	EC56
Note	
Type	Service Campaign
US code	

Vehicle data

Flying Spur and Bentayga Series

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2020	E		*	*	*
ZG2*	2020	E		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SJA	*	*	*	L	C	027868	032134		
SCB	*	*	*	L	C	078663	084744		

Documents

Document name
master.xml
sc2231vinlist.pdf

Notes



Technical background

On vehicles specified with Rear Seat Entertainment (RSE) a software update is required, the update should be applied to both RSE tablets

Remedy

All vehicles affected by this campaign require the software of both RSE tablets updating

Customer notification

Keepers of affected vehicles will be notified in writing by their Bentley retailer to arrange an appointment

If it is omitted to perform the work required during a workshop visit, the customer should be notified immediately

You should also pass on this information to your new and used car sales departments so that affected vehicles are checked and repaired immediately

Warranty accounting instructions

Time to update both RSE tablets

Warranty Type	790 or 710
Damage Service Number	EC 56
Damage Code	00 66
Labour Operation Code	01 51 00 00
Criteria 01	
Time	50 TU

Genuine parts

Not applicable

Parts supply

Not applicable

Parts despatch control

Not applicable

Repair instructions



Technical background

On vehicles specified with Rear Seat Entertainment (RSE) a software update is required, the update should be applied to both RSE tablets

Check

If the vehicle is not already listed as repaired in the "Repair history" (Elsa pro) check for the presence of a green paint completion mark (see Identification section)

Genuine parts

Not applicable

Tools

USB to Micro USB cable (Figure 1) source locally



Figure 1

Work



Please Note: The procedure does not and must not be used in an attempt to rectify any RSE system faults

A fault free and fully functioning RSE system is required before applying this campaign, therefore the system must be tested, any faults found within the RSE system MUST be rectified before applying this procedure

1) Access the Bentley Hub

New Flying Spur

- Referring to Figure 2 - the applicable zip file can be found in >Aftersales > Diagnostics & Electrical > SDIS_Update_631




Figure 2

2) Extract the Zip file SDIS 631.zip onto the C drive of the applicable PC/laptop (Figure 3)




Figure 3

Bentayga

- Referring to Figure 4 - the applicable zip file can be found in >Aftersales > Diagnostics & Electrical > SDIS_Update_636




Figure 4

- Extract the Zip file SDIS 636.zip onto the C drive of the applicable PC/laptop (Figure 5)




Figure 5



VERY IMPORTANT: The software update MUST be conducted on both RSE tablets



VERY IMPORTANT: Ensure the RSE tablet battery of both RSE tablets is fully charged before starting the updates

Or

Docked within the vehicle

Left hand RSE tablet

3) Complete the following steps to update the left hand RSE tablet



IMPORATANT: Make sure the device is switched off. If not, switch it off by pressing the Power key for more than 15 seconds

4) Referring to Figure 6 - Change the RSE tablet to the bootloader menu as follows:

- Press and hold the Power key
- With the power key held, Press the volume down key (-) as frequently as possible




Figure 6

- The bootloader menu when evident should be as shown in Figure 7
- Select "Recovery kernel" in bootloader menu by pressing the Volume (-) down key several times - Confirm your selection by pressing the Power key



Figure 7

5) Once a green Android robot is shown (Figure 8) the operative should press the following key/key combination depending on your Android version:

- 1st try - pressing the Power key to display the recovery kernel menu
- If the above is not successful - Hold the Power key down while pressing the Volume up key shortly to display the recovery kernel menu




Figure 8

- Navigate to the recovery kernel menu by pressing the Volume down key and confirm your selection by pressing the Power key
- Select “apply update from ADB.” (Figure 9)




Figure 9

6) Connect the RSE tablet to the PC/laptop via a micro USB cable into the Micro USB port (Figure 6)

IMPORTANT HINT: The following prompts must be performed from the operative PC/laptop

- Navigate to the applicable 631 SDIS update file
- Double click the update file whilst following the commands on the script (Figure 10)



VERY IMPORTANT: Wait until the re-flash has reached 100% before continuing




Figure 10

7) Once the update has reached 100% the Window will request the operative to press another key to continue - Close the window (using 'X' button)

8) Once the update is finished, reboot the device (Figure 11)




Figure 11

9) Switch off the device by pressing the Power key for more than 15 seconds

- Switch the device back on (with the power key) to check for the Android logo - Then switch the device off

10) To prevent high consumption of the RSE tablets batteries, please also ensure the onward instructions are followed on both RSE tablets:

- Select "Settings" on home screen
- Select "Location" (Figure 12)




Figure 12

- Select "Mode" (Figure 13)



Figure 13

- The “Mode” is likely set to ‘High Accuracy’ (Figure 14)




Figure 14

- Please ensure the “Mode” is set to ‘DEVICE ONLY’ (Figure 15)




Figure 15

- 11) Repeat steps 3 to 10 on the right hand RSE tablet
- 12) Place a green paint completion mark on the left hand rear door electrical connection (Figure 16)

Identification



Figure 16

NOTE: The example shows a Bentayga rear door electrical connection the paint mark should be applied in the same location on New Flying Spur vehicles

▲ Repair instructions ▲ Notes

Bentayga

SJAAB14V3LC027868	SJAAN14V9LC028837	SJAAL1ZV1LC029477	SJAAL14V0LC030174	SJAAP14VXLC031031
SJAAL14V0LC027971	SJAAL1ZV7LC028849	SJAAN1ZV4LC029483	SJAAH14V9LC030188	SJAAH14V4LC031040
SJAAB14V6LC027976	SJAAB14V6LC028853	SJAAN1ZV1LC029490	SJAAH14V0LC030192	SJAAL1ZV1LC031049
SJAAL1ZV0LC027980	SJAAP14V6LC028854	SJAAL1ZV9LC029517	SJAAB14V7LC030210	SJAAH14V6LC031055
SJAAL1ZV4LC027982	SJAAH14V1LC028855	SJAAN14V9LC029535	SJAAH14V1LC030217	SJAAH14V5LC031080
SJAAB14V3LC027983	SJAAP34V7LC028857	SJAAN1ZV3LC029541	SJAAB14VXLC030248	SJAAP14VXLC031093
SJAAL14V2LC027986	SJAAN14V4LC028860	SJAAN1ZV1LC029554	SJAAH14V0LC030256	SJAAH14VXLC031107
SJAAB14V9LC028040	SJAAH14V0LC028863	SJAAN1ZV4LC029578	SJAAL1ZV9LC030263	SJAAB34V4LC031116
SJAAL14V2LC028085	SJAAF1ZV7LC028891	SJAAP14V6LC029602	SJAAL1ZV6LC030267	SJAAB14V2LC031121
SJAAL1ZV3LC028122	SJAAP14V3LC028892	SJAAH14V0LC029611	SJAAB14V4LC030276	SJAAH14V6LC031136
SJAAB14V0LC028136	SJAAB14V2LC028896	SJAAP14V1LC029619	SJAAH14V6LC030312	SJAAL1ZV1LC031178
SJAAL1ZV0LC028143	SJAAN1ZV8LC028904	SJAAP14V8LC029648	SJAAP14V8LC030315	SJAAF1ZV3LC031223
SJAAL1ZV2LC028144	SJAAN1ZV5LC028908	SJAAN1ZV4LC029659	SJAAB14V1LC030316	SJAAP14V1LC031225
SJAAL1ZV2LC028208	SJAAH14V2LC028914	SJAAK14V7LC029672	SJAAH14V7LC030318	SJAAH14VXLC031236
SJAAB14V8LC028238	SJAAH14VXLC028918	SJAAB34V3LC029678	SJAAR2ZV4LC030319	SJAAH14V0LC031262
SJAAL1ZV9LC028254	SJAAN1ZV6LC028920	SJAAN14V3LC029692	SJAAB14V2LC030325	SJAAH14V4LC031300
SJAAH14V5LC028308	SJAAB14V5LC028925	SJAAN1ZV0LC029710	SJAAB14V1LC030333	SJAAH14VXLC031303
SJAAF1ZVXLC028318	SJAAL1ZVXLC028943	SJAAB14V2LC029711	SJAAL1ZV0LC030359	SJAAH14V1LC031335
SJAAH14V6LC028320	SJAAH14V3LC028954	SJAAN1ZV3LC029717	SJAAH14V5LC030365	SJAAF1ZV7LC031337
SJAAP14V7LC028328	SJAAH14V9LC028974	SJAAP14V0LC029725	SJAAL14V8LC030391	SJAAB34V0LC031338
SJAAF1ZV4LC028377	SJAAM2ZV3LC028981	SJAAP14V6LC029728	SJAAP14V8LC030394	SJAAL3ZV6LC031351
SJAAF14V7LC028395	SJAAH14V5LC028986	SJAAB14V8LC029745	SJAAH14V7LC030416	SJAAL1ZV9LC031381
SJAAP34V1LC028403	SJAAL1ZVXLC029008	SJAAL1ZV2LC029746	SJAAP14V7LC030418	SJAAH14VXLC031382
SJAAB14V8LC028420	SJAAH14V2LC029013	SJAAH14V3LC029747	SJAAL14VXLC030442	SJAAL14V0LC031387
SJAAL1ZV7LC028429	SJAAH14V1LC029018	SJAAL1ZV9LC029761	SJAAP14V9LC030470	SJAAB34V8LC031393
SJAAB14V4LC028432	SJAAN14V4LC029023	SJAAR2ZV8LC029769	SJAAH14V3LC030493	SJAAH14V1LC031402
SJAAL1ZV6LC028440	SJAAP14V3LC029024	SJAAN1ZV2LC029773	SJAAB14V7LC030496	SJAAN1ZV8LC031429
SJAAF1ZVXLC028447	SJAAN1ZV0LC029027	SJAAP14V4LC029775	SJAAN1ZV0LC030548	SJAAB14V6LC031431
SJAAL1ZV0LC028465	SJAAM2ZV7LC029048	SJAAR2ZV0LC029782	SJAAH14V9LC030563	SJAAL14V3LC031433
SJAAP14V5LC028473	SJAAH14V8LC029050	SJAAH14V8LC029789	SJAAB14V9LC030564	SJAAJ2ZVXLC031465
SJAAP14V8LC028483	SJAAF14VXLC029055	SJAAN1ZV4LC029791	SJAAB14V7LC030580	SJAAL14V5LC031501
SJAAP14V3LC028486	SJAAH14V4LC029062	SJAAP14V3LC029847	SJAAN14V4LC030589	SJAAM2ZV5LC031512
SJAAL14V8LC028494	SJAAH14V7LC029072	SJAAL1ZV0LC029860	SJAAL14VXLC030621	SJAAH14V0LC031519
SJAAF1ZV2LC028507	SJAAH14V8LC029078	SJAAN14V2LC029862	SJAAL14V3LC030640	SJAAM2ZV6LC031521
SJAAP34V2LC028541	SJAAN1ZV1LC029098	SJAAP14V7LC029866	SJAAP34V9LC030660	SJAAH14V2LC031523
SJAAB14V2LC028543	SJAAN1ZVXLC029102	SJAAN1ZV5LC029900	SJAAP14V5LC030692	SJAAH14V8LC031526
SJAAL14VXLC028545	SJAAL1ZV3LC029139	SJAAL1ZV0LC029910	SJAAP14V9LC030694	SJAAP14V6LC031527
SJAAF1ZV7LC028552	SJAAH14V7LC029153	SJAAL1ZV8LC029914	SJAAH14V8LC030702	SJAAH14VXLC031530
SJAAL14V8LC028589	SJAAW14V3LC029172	SJAAH14V9LC029915	SJAAL14V9LC030710	SJAAH14V3LC031532
SJAAB14V0LC028640	SJAAH14V6LC029175	SJAAL14V6LC029918	SJAAN14V2LC030722	SJAAB14V0LC031537
SJAAB14V3LC028647	SJAAB14VXLC029181	SJAAL1ZV2LC029925	SJAAL14V2LC030774	SJAAH14VXLC031544
SJAAL1ZV3LC028671	SJAAN14VXLC029186	SJAAN1ZV5LC029945	SJAAL1ZV0LC030779	SJAAL14V7LC031547
SJAAP14V2LC028673	SJAAW14V4LC029231	SJAAP14V7LC029950	SJAAB14V3LC030821	SJAAL14V2LC031553
SJAAH14V5LC028681	SJAAL1ZVXLC029249	SJAAL1ZV9LC029954	SJAAH14V5LC030852	SJAAM2ZV1LC031555
SJAAP14V7LC028703	SJAAL1ZV8LC029282	SJAAL1ZV0LC029955	SJAAN1ZV0LC030856	SJAAH14VXLC031561
SJAAB14V1LC028727	SJAAL14V5LC029294	SJAAL1ZV0LC029972	SJAAL14V6LC030857	SJAAH14V7LC031565
SJAAP14V2LC028737	SJAAL1ZV2LC029312	SJAAW14V5LC029982	SJAAP14V2LC030861	SJAAB14V0LC031571
SJAAB14V6LC028738	SJAAP14V7LC029317	SJAAH14V8LC029985	SJAAL14V5LC030879	SJAAH14V6LC031573
SJAAB14V9LC028782	SJAAH14V4LC029319	SJAAL1ZV5LC030003	SJAAB14VXLC030881	SJAAH14V8LC031588
SJAAP14V0LC028784	SJAAN1ZV8LC029325	SJAAL1ZV8LC030030	SJAAN1ZV0LC030887	SJAAB34VXLC031590
SJAAP14V6LC028787	SJAAL1ZV6LC029362	SJAAB14V4LC030066	SJAAP14V0LC030941	SJAAM2ZV5LC031591
SJAAM2ZVXLC028797	SJAAP14V2LC029399	SJAAL1ZV3LC030078	SJAAL14V0LC030949	SJAAH14V5LC031600
SJAAB14V8LC028806	SJAAN1ZV4LC029404	SJAAL1ZVXLC030126	SJAAB14V2LC030955	SJAAP14VXLC031613
SJAAR2ZV9LC028808	SJAAN1ZV0LC029450	SJAAB14V4LC030150	SJAAB14V9LC030984	SJAAH14V5LC031614
SJAAP14V4LC028822	SJAAN1ZV6LC029470	SJAAN1ZVXLC030153	SJAAH14V9LC030997	SJAAP14V5LC031616
SJAAJ2ZV7LC028829	SJAAB14V5LC029475	SJAAN1ZV7LC030160	SJAAH14VXLC031026	SJAAB14V9LC031617

INTERNAL

SJAAH14V2LC031621	SJAAH14VXLC031687	SJAAH14V8LC031848	SJAAB14V8LC031995	SJAAH14V0LC032069
SJAAM2ZV5LC031624	SJAAP34V4LC031702	SJAAH14V6LC031878	SJAAP14V3LC031999	SJAAL3ZV2LC032075
SJAAH14VXLC031625	SJAAH14V1LC031710	SJAAH14VXLC031916	SJAAH14V8LC032014	SJAAH14V0LC032086
SJAAH14V4LC031636	SJAAH14V6LC031721	SJAAH14V1LC031951	SJAAH14V3LC032017	SJAAL14V5LC032096
SJAAB14V6LC031641	SJAAH14V1LC031724	SJAAH14V7LC031954	SJAAH14V8LC032031	SJAAH14V3LC032129
SJAAB14V5LC031646	SJAAH14V7LC031730	SJAAH14V2LC031957	SJAAB14V9LC032038	SJAAP14V3LC032134
SJAAM2ZV6LC031650	SJAAL14V8LC031735	SJAAH14V9LC031972	SJAAP14V1LC032052	
SJAAB34V9LC031659	SJAAH14V1LC031741	SJAAH14V0LC031987	SJAAH14V2LC032056	
SJAAR4ZV0LC031673	SJAAL14V2LC031746	SJAAB14V0LC031988	SJAAL14V6LC032057	
SJAAH14V8LC031686	SJAAL14V3LC031755	SJAAH14V0LC031990	SJAAB14V8LC032063	

Flying Spur

SCBBA53SXL078663	SCBBB6ZG9LC079907	SCBBA53S3LC080528	SCBBA5ZGXL080903	SCBBS53S6LC081461
SCBBS53S3LC078677	SCBBB6ZG9LC079910	SCBBA5ZG8LC080530	SCBBS53S6LC080911	SCBBA5ZG6LC081482
SCBBS53S8LC078934	SCBBB6ZG6LC079914	SCBBA53S6LC080541	SCBBS53S9LC080918	SCBBS53S6LC081492
SCBBS53S9LC078943	SCBBB6ZG5LC079919	SCBBA5ZG3LC080550	SCBBA5ZGXL080920	SCBBB6ZG6LC081498
SCBBS53S5LC079118	SCBBB6ZG1LC079934	SCBBA53S0LC080552	SCBBB6ZG2LC080932	SCBBA5ZG8LC081502
SCBBA53S7LC079124	SCBBS53S0LC079995	SCBBA5ZG6LC080557	SCBBA53S5LC080949	SCBBS53S4LC081510
SCBBS53S9LC079154	SCBBB6ZG3LC080003	SCBBS53S9LC080563	SCBBA53S2LC080990	SCBBB6ZG8LC081518
SCBBA53S4LC079159	SCBBB6ZG0LC080007	SCBBA5ZG0LC080571	SCBBB6ZG4LC081001	SCBBB6ZG5LC081539
SCBBA53S3LC079198	SCBBB6ZG4LC080012	SCBBA5ZG4LC080573	SCBBA53S2LC081007	SCBBS53S8LC081543
SCBBA53S3LC079329	SCBBB6ZG5LC080021	SCBBS53S5LC080589	SCBBA53S6LC081012	SCBBA5ZG4LC081545
SCBBA53S1LC079331	SCBBS53S5LC080043	SCBBA5ZG8LC080592	SCBBA5ZG8LC081015	SCBBA53S5LC081549
SCBBA53S5LC079333	SCBBS53S4LC080051	SCBBS53S4LC080616	SCBBS53S3LC081028	SCBBS53SXL081558
SCBBS53S0LC079348	SCBBB6ZG9LC080071	SCBBS53SXL080622	SCBBS53S4LC081054	SCBBA5ZG1LC081566
SCBBS53S9LC079462	SCBBB6ZG4LC080074	SCBBS53S3LC080638	SCBBA5ZG4LC081075	SCBBS53S8LC081588
SCBBB6ZG3LC079630	SCBBS53S7LC080092	SCBBA5ZG1LC080644	SCBBS53S9LC081079	SCBBS53S9LC081602
SCBBB6ZG5LC079631	SCBBB6ZG9LC080135	SCBBS53S2LC080646	SCBBA5ZGXL081100	SCBBA5ZG0LC081607
SCBBB6ZG9LC079633	SCBBS53SXL080202	SCBBS53S4LC080650	SCBBA5ZG3LC081102	SCBBA5ZGXL081629
SCBBB6ZGXL079642	SCBBS53S6LC080214	SCBBA53S4LC080652	SCBBB6ZG6LC081114	SCBBS53S5LC081631
SCBBB6ZG4LC079653	SCBBA5ZG3LC080239	SCBBS53SXL080670	SCBBB6ZG1LC081120	SCBBA5ZG0LC081641
SCBBB6ZG5LC079659	SCBBB6ZG9LC080250	SCBBA5ZG8LC080690	SCBBS53S3LC081126	SCBBA5ZG5LC081666
SCBBB6ZG6LC079668	SCBBB6ZG3LC080275	SCBBA53S1LC080723	SCBBS53S7LC081145	SCBBS53S1LC081691
SCBBA53S5LC079686	SCBBA5ZG2LC080300	SCBBS53S9LC080725	SCBBA5ZG3LC081147	SCBBA5ZG1LC081695
SCBBB6ZG7LC079713	SCBBA5ZGXL080304	SCBBS53S9LC080739	SCBBS53S2LC081151	SCBBA5ZG3LC081701
SCBBB6ZG1LC079738	SCBBS53S2LC080310	SCBBA5ZG0LC080750	SCBBA5ZG1LC081177	SCBBA5ZG0LC081705
SCBBB6ZG6LC079752	SCBBB6ZG8LC080322	SCBBS53S7LC080755	SCBBB6ZGXL081200	SCBBA53S1LC081709
SCBBB6ZG2LC079764	SCBBB6ZG5LC080326	SCBBS53S0LC080760	SCBBS53S6LC081203	SCBBA5ZG1LC081714
SCBBB6ZGXL079768	SCBBA5ZG2LC080328	SCBBS53S5LC080771	SCBBA5ZG3LC081214	SCBBS53S4LC081720
SCBBB6ZG7LC079775	SCBBS53S4LC080339	SCBBA5ZG0LC080778	SCBBS53S0LC081245	SCBBS53S9LC081731
SCBBA53S1LC079779	SCBBB6ZG5LC080343	SCBBA5ZG6LC080784	SCBBA5ZG4LC081254	SCBBA5ZG8LC081743
SCBBB6ZG9LC079793	SCBBB6ZG1LC080369	SCBBA5ZG1LC080790	SCBBA5ZG6LC081272	SCBBA5ZG2LC081771
SCBBB6ZG6LC079797	SCBBA5ZGXL080383	SCBBA53S8LC080802	SCBBS53S3LC081286	SCBBA5ZG1LC081776
SCBBB6ZG9LC079809	SCBBB6ZGXL080399	SCBBA5ZG7LC080812	SCBBA5ZG4LC081299	SCBBA5ZG7LC081801
SCBBB6ZG7LC079811	SCBBB6ZG4LC080401	SCBBA5ZG4LC080816	SCBBA5ZG2LC081303	SCBBA5ZGXL081808
SCBBB6ZG4LC079815	SCBBB6ZG4LC080415	SCBBA5ZGXL080822	SCBBA5ZG3LC081312	SCBBA5ZG8LC081810
SCBBB6ZG1LC079819	SCBBB6ZG5LC080441	SCBBS53S0LC080824	SCBBA5ZG4LC081318	SCBBA5ZG7LC081832
SCBBB6ZG3LC079823	SCBBB6ZGXL080449	SCBBS53S4LC080826	SCBBS53S4LC081345	SCBBS53S3LC081840
SCBBB6ZG0LC079827	SCBBA5ZG9LC080455	SCBBA5ZG2LC080846	SCBBA5ZG7LC081362	SCBBS53S2LC081845
SCBBB6ZG2LC079831	SCBBA5ZG5LC080467	SCBBA5ZG4LC080850	SCBBA5ZG5LC081375	SCBBS53S2LC081893
SCBBB6ZG5LC079841	SCBBA5ZG4LC080475	SCBBS53S9LC080854	SCBBB6ZG5LC081377	SCBBA5ZG6LC081921
SCBBB6ZGXL079849	SCBBA5ZGXL080481	SCBBA53S9LC080856	SCBBA5ZG0LC081381	SCBBA53S9LC081957
SCBBB6ZG1LC079853	SCBBA5ZG8LC080494	SCBBA5ZG9LC080858	SCBBA5ZG1LC081390	SCBBA5ZG9LC081959
SCBBA53S9LC079870	SCBBS53S1LC080508	SCBBA5ZG7LC080860	SCBBA53S2LC081394	SCBBB6ZG0LC081965
SCBBB6ZG9LC079874	SCBBS53S0LC080516	SCBBA5ZG5LC080873	SCBBA5ZG5LC081439	SCBBA5ZG1LC081969
SCBBB6ZG6LC079900	SCBBS53S4LC080518	SCBBS53S8LC080893	SCBBA5ZG6LC081448	SCBBA5ZG4LC081982
SCBBB6ZG5LC079905	SCBBA5ZG9LC080522	SCBBS53S3LC080901	SCBBA5ZGXL081453	SCBBA5ZG2LC082015

INTERNAL

SCBBB6ZG8LC082023	SCBBS53S9LC082460	SCBBS53S4LC082916	SCBBS53S9LC083429	SCBBS53S0LC084078
SCBBA5ZG3LC082038	SCBBS53S2LC082462	SCBBA53S6LC082922	SCBBA53S3LC083431	SCBBA5ZG1LC084080
SCBBA5ZG6LC082048	SCBBA5ZG9LC082464	SCBBB6ZG7LC082935	SCBBS53S0LC083433	SCBBA5ZG1LC084094
SCBBB6ZG0LC082050	SCBBA5ZG3LC082475	SCBBA5ZG4LC082937	SCBBS53S9LC083446	SCBBS53S2LC084115
SCBBA5ZG1LC082054	SCBBA53S6LC082483	SCBBA5ZG5LC082946	SCBBS53S1LC083487	SCBBA5ZG8LC084139
SCBBB6ZG7LC082062	SCBBA5ZG0LC082496	SCBBA53S4LC082949	SCBBS53SXLC083522	SCBBA5ZGXLC084143
SCBBA53S7LC082072	SCBBA5ZG2LC082502	SCBBS53S9LC082961	SCBBS53S9LC083530	SCBBA5ZG0LC084152
SCBBA5ZG1LC082085	SCBBS53S6LC082514	SCBBS53SXLC082967	SCBBS53S1LC083540	SCBBA5ZG0LC084166
SCBBS53S2LC082087	SCBBA5ZG2LC082516	SCBBA5ZG6LC082969	SCBBS53S2LC083546	SCBBA53S3LC084191
SCBBA5ZG9LC082089	SCBBS53S3LC082518	SCBBA5ZG8LC082973	SCBBS53S9LC083575	SCBBA5ZG4LC084199
SCBBS53S3LC082101	SCBBS53S1LC082520	SCBBA5ZG1LC082975	SCBBA53S0LC083595	SCBBA5ZG0LC084202
SCBBA5ZGXLC082117	SCBBS53S6LC082531	SCBBS53S2LC082994	SCBBS53S9LC083608	SCBBS53S1LC084204
SCBBA5ZG5LC082123	SCBBA5ZG2LC082533	SCBBA53S6LC082998	SCBBS53S3LC083619	SCBBA5ZG1LC084208
SCBBS53SXLC082130	SCBBB6ZG9LC082547	SCBBS53S4LC083001	SCBBB6ZG6LC083638	SCBBS53S7LC084210
SCBBA5ZGXLC082134	SCBBS53S3LC082552	SCBBS53S7LC083011	SCBBS53S8LC083650	SCBBA5ZG1LC084211
SCBBA5ZG7LC082138	SCBBS53S7LC082554	SCBBA5ZG5LC083014	SCBBB6ZG3LC083659	SCBBA5ZG9LC084215
SCBBA5ZG5LC082140	SCBBA5ZG7LC082561	SCBBS53S7LC083025	SCBBS53S6LC083663	SCBBS53S1LC084218
SCBBS53S7LC082151	SCBBA5ZG0LC082580	SCBBA5ZG7LC083032	SCBBS53S6LC083677	SCBBA5ZG7LC084228
SCBBA5ZG7LC082155	SCBBA53S8LC082582	SCBBA5ZG9LC083050	SCBBS53S8LC083678	SCBBA5ZG8LC084237
SCBBA53S1LC082164	SCBBA53S0LC082592	SCBBS53S8LC083051	SCBBS53S5LC083685	SCBBA5ZG8LC084254
SCBBA5ZG7LC082172	SCBBS53S8LC082594	SCBBS53S9LC083060	SCBBA53S3LC083686	SCBBS53SXLC084265
SCBBA5ZG1LC082183	SCBBB6ZG2LC082602	SCBBS53S4LC083063	SCBBA53S2LC083694	SCBBS53S5LC084304
SCBBA53S2LC082187	SCBBA5ZG3LC082623	SCBBB6ZG2LC083071	SCBBS53S6LC083713	SCBBS53S1LC084316
SCBBS53S2LC082199	SCBBA53S3LC082635	SCBBS53S4LC083077	SCBBA53S0LC083726	SCBBA5ZG5LC084339
SCBBB6ZG0LC082209	SCBBB6ZG8LC082636	SCBBS53S4LC083077	SCBBA53S0LC083726	SCBBA5ZG5LC084339
SCBBA53SXLC082213	SCBBA5ZG1LC082653	SCBBA5ZG6LC083085	SCBBS53S3LC083751	SCBBS53S2LC084373
SCBBS53S0LC082217	SCBBA5ZG2LC082659	SCBBS53SXLC083097	SCBBS53S6LC083761	SCBBS53SXLC084377
SCBBS53S2LC082235	SCBBA53S9LC082669	SCBBA5ZG1LC083110	SCBBS53S3LC083765	SCBBS53S7LC084384
SCBBS53S5LC082245	SCBBS53S5LC082679	SCBBS53S9LC083124	SCBBS53S2LC083773	SCBBS53S0LC084386
SCBBS53S4LC082253	SCBBB6ZG1LC082686	SCBBA5ZG3LC083125	SCBBS53SXLC083777	SCBBS53S6LC084392
SCBBA5ZG0LC082255	SCBBS53S1LC082694	SCBBS53S4LC083158	SCBBA5ZG4LC083778	SCBBA53S8LC084395
SCBBA5ZG4LC082257	SCBBA5ZG3LC082704	SCBBS53S6LC083159	SCBBA53S8LC083781	SCBBA5ZG7LC084438
SCBBS53S8LC082269	SCBBA5ZG9LC082707	SCBBS53S7LC083168	SCBBA53S2LC083789	SCBBS53SXLC084444
SCBBA5ZGXLC082280	SCBBS53S3LC082714	SCBBS53S5LC083170	SCBBA53S8LC083795	SCBBS53S1LC084445
SCBBS53S4LC082284	SCBBA5ZGXLC082716	SCBBA5ZG6LC083197	SCBBS53S0LC083805	SCBBA53S3LC084448
SCBBB6ZG0LC082288	SCBBS53S1LC082730	SCBBA5ZG4LC083201	SCBBA5ZG7LC083807	SCBBA5ZG1LC084452
SCBBS53SXLC082290	SCBBS53S9LC082734	SCBBA5ZG4LC083215	SCBBS53S5LC083816	SCBBA53S4LC084457
SCBBA5ZG9LC082304	SCBBS53S0LC082735	SCBBA5ZGXLC083218	SCBBS53S3LC083846	SCBBA5ZG4LC084462
SCBBA5ZG8LC082309	SCBBA53S0LC082737	SCBBA5ZGXLC083221	SCBBS53S5LC083847	SCBBS53S3LC084463
SCBBA53S4LC082322	SCBBA5ZG2LC082743	SCBBS53S4LC083225	SCBBA5ZG1LC083849	SCBBA53S3LC084465
SCBBA5ZG4LC082324	SCBBB6ZG8LC082748	SCBBS53S9LC083236	SCBBS53S5LC083850	SCBBA5ZG7LC084472
SCBBA5ZGXLC082330	SCBBB6ZG6LC082750	SCBBA5ZG1LC083284	SCBBS53S0LC083867	SCBBA5ZG4LC084476
SCBBS53S4LC082334	SCBBS53S0LC082752	SCBBA53S9LC083286	SCBBS53S1LC083876	SCBBA53S1LC084478
SCBBS53S1LC082338	SCBBA5ZG6LC082762	SCBBA5ZG0LC083289	SCBBS53S3LC083930	SCBBA53SXLC084480
SCBBS53S7LC082344	SCBBA5ZG3LC082766	SCBBA5ZG0LC083292	SCBBA53S7LC083934	SCBBA53S6LC084492
SCBBA53S7LC082346	SCBBA5ZG7LC082771	SCBBS53S1LC083294	SCBBS53S7LC083946	SCBBS53S5LC084495
SCBBA53S0LC082348	SCBBA53S9LC082798	SCBBA5ZG6LC083295	SCBBS53S0LC083948	SCBBS53S2LC084499
SCBBA5ZG7LC082365	SCBBS53S1LC082808	SCBBA5ZG1LC083303	SCBBA5ZG5LC083966	SCBBA5ZG3LC084503
SCBBA5ZG0LC082367	SCBBS53S4LC082821	SCBBS53S1LC083327	SCBBA53S2LC083971	SCBBS53S0LC084520
SCBBS53S3LC082373	SCBBA5ZG7LC082835	SCBBS53S1LC083330	SCBBA5ZG3LC083996	SCBBA5ZG0LC084541
SCBBA5ZG8LC082391	SCBBS53S3LC082857	SCBBA53S9LC083336	SCBBA53S7LC084002	SCBBA5ZG8LC084559
SCBBS53S2LC082395	SCBBA53S7LC082864	SCBBS53S7LC083347	SCBBS53S4LC084004	SCBBS53SXLC084573
SCBBA5ZG5LC082400	SCBBA5ZG7LC082866	SCBBS53S8LC083390	SCBBA5ZG4LC084025	SCBBS53S4LC084584
SCBBS53S8LC082417	SCBBA5ZG0LC082868	SCBBA53S9LC083398	SCBBA5ZG8LC084027	SCBBA53S6LC084587
SCBBA5ZG2LC082421	SCBBA53S5LC082877	SCBBS53S4LC083399	SCBBA53S8LC084039	SCBBA5ZG4LC084588
SCBBA53S2LC082433	SCBBA53S8LC082887	SCBBA5ZG2LC083407	SCBBA5ZG5LC084048	SCBBS53S0LC084596
SCBBA5ZG2LC082449	SCBBS53S5LC082889	SCBBA53S6LC083424	SCBBS53S3LC084060	SCBBS53S5LC084612

INTERNAL

SCBBA5ZG3LC084615	SCBBS53S7LC084630	SCBBS53S9LC084645	SCBBS53S3LC084656	SCBBA53S0LC084665
SCBBS53S6LC084618	SCBBA53S0LC084634	SCBBS53S0LC084646	SCBBS53S9LC084659	SCBBS53S0LC084677
SCBBS53S8LC084622	SCBBA5ZG2LC084640	SCBBS53S8LC084653	SCBBS53S7LC084661	SCBBA5ZG3LC084744
SCBBS53S7LC084627	SCBBA5ZG8LC084643	SCBBS53S1LC084655	SCBBA53S9LC084664	