

TO: Freightliner Dealers, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Service Campaign Notification Model 907 Sprinter Model Years 2019-2022 Update Vehicle Software	DATE: January, 2023

IMPORTANT SERVICE CAMPAIGN INFORMATION

Campaign No. :	Campaign Desc. :	Update Software
2022120009	22V2790614	
<p>This is to notify you of the upcoming Service Campaign to update software on approximately 124,079 MY 2019-2021 Freightliner Sprinter vans. All affected VINs will be flagged as "OPEN" in VMI.</p>		
Background		
Issue	<p>In addition to the recalls 2790611, 2790612 and 2790613 regarding the "Automatic transmission – Park pawl function", this service measure gets applied simultaneously along with the above mentioned recalls. This service measure will provide an alert to the driver in the event that the vehicle is not properly secured (according to the parking instructions in the operator’s manual; vehicle in “park” with the manual parking brake set).</p>	
What We’re Doing	<p>An authorized Freightliner dealer will update the software of various control units (incl. the ESP and transmission control units) in the affected vehicles.</p> <p>Please close out the service campaign using op code 02-2442 & 0.1hr, along with damage code 27 906 14. Because this measure is bundled with the previously launched “Park Pawl Function” recalls (2790611/2/3), there is no additional action required at the workshop.</p>	
Parts	Software is Available	
Vehicles Affected		
Vehicle Model Year(s)	2019-2022	
Vehicle Model	907 Sprinter	
Vehicle Populations		
Total Vehicles	5,555	
Next Steps/Notes		
AOMS/SOMS	Please ensure your dealers have read and understand this notice	
<p>While we regret any inconvenience this may cause, DVUSA are determined to maintain a high level of vehicle quality and customer satisfaction.</p>		