



Mack Chassis - TerraPro (MRU) And Low Entry (LEU) Models - Field Service Bulletin FSB 381-042, Warning Light Bar (WLB) Replacement and Software Conversion Kit - US07, US10, US10+OBD13, US14+OBD13 To US14+OBD16 Emissions, Model Years 2008 To 2017



Internal Content

DEALER ID: A241298
CREATED BY: A241298
CREATED: Sep 20, 2018, 06:10PM
LAST CHANGED BY: RU4469V
LAST CHANGED: Nov 26, 2019, 05:51PM
NEXT REVIEW: Jan 05, 2020, 11:00PM

Field Service Bulletin FSB 381-042 is located under the Service tab in [Impact](#).

NOTE: Please make certain the latest P/N is being used.

Tags [fsb 381-042](#) [k44714632](#) [mack](#) [wlb](#)

Categories

Mack > US14 > US14+OBD13 > LEU > Body and Cab > Exterior

Mack > US14 > US14+OBD13 > MRU > Body and Cab > Exterior

Mack > US14 > US14+OBD15 > LR > Body and Cab > Exterior

Mack > US14 > US14+OBD15 > MRU > Body and Cab > Exterior

Live UI > US14 > US14+OBD16 > LR > Body and Cab > Exterior

Mack > US14 > US14+OBD16 > MRU > Body and Cab > Exterior

Mack > US10 > LEU > Body and Cab > Exterior

Mack > US10 > MRU > Body and Cab > Exterior

Mack > US10+OBD13 > LEU > Body and Cab > Exterior

Mack > US10+OBD13 > MRU > Body and Cab > Exterior

Related links and attachments

[FSB381-042_M](#)



Feedback

[Give feedback](#)

to help improve the content of this article



Date	Group	No.	Release	Page
12.2011	381	042	01	1(1)

Warning Light Bar Replacement and Software Conversion Kit

FSB 381-042, Warning Light Bar Replacement and Software Conversion Kit ^{MRU, LEU}

(December 2011)

When replacing the Warning Light Bar (WLB) use the following chart to order the required accessory kit.

Replacement Hardware RH	Replacement Hardware LH	Kit Number
21030614	21026336	85133188
21198836	21198834	85133190
21165272	21165271	85133191
21424815	21424814	85133191
21656491 with Software 21650156 or less	21656490 with Software 21650156 or less	85133191
21656491 with Software 21732358 or greater	21656490 with Software 21732358 or greater	85133192

Note: If a dual drive vehicle is requiring a new WLB, both WLB's must match. Use the above table to match the left hand (LH) and right hand (RH) hardware.