



INFINITI

TECHNICAL SERVICE BULLETIN

Classification: DA21-008A	Reference: ITB21-025A	Date: March 9, 2023
------------------------------	--------------------------	------------------------

DTC C1A17-49 STORED IN LASER/RADAR

This bulletin has been amended. See AMENDMENT HISTORY on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2017-2022 Q60 (CV37)
2019-2023 QX50 (J55)
2022-2023 QX55 (FJ55)
2015-2023 QX80 (Z62)

SERVICE INFORMATION

If DTC C1A17-49 (ICC SENSOR MALF / CONTROL UNIT) is stored in LASER/RADAR in the "PAST" column:

- Erase the DTC.
- DO NOT replace any parts.

If DTC C1A17-49 is stored in LASER/RADAR in the "CURRENT" column, refer to the applicable ESM for instructions.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 15, 2021	ITB21-025	Original bulletin published
March 9, 2023	ITB21-025A	APPLIED VEHICLES and DTC descriptions revised

