



Service Bulletin

Bulletin No.: 23-NA-052

Date: March, 2023

INFORMATION

Subject: Information on Transfer Case Cost Comparison Instruction

This bulletin replaces PIP5825. Please discard PIP5825.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 4500 HD/ 5500 HD/6500 HD	2019	2022	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	NQF
Condition	A vehicle may come in with a transfer case concern.
Cause	Possible Internal transfer case concern.
Correction	<p>For shifting concern, please review the latest version of PIP5853B: TCCM Drivability DTCs and Possible Low Battery Charge</p> <p>Internal transfer case concerns, the dealer will need to disassemble to the point of failure and then do a cost comparison to determine repair VS replacement.</p> <ul style="list-style-type: none"> • If the cost of the repair is less then the replacement, repair the unit. • If the cost of the repair exceeds the price of the unit, replace the unit. <p>– Refer to the Transfer Case Cost Comparison Worksheet in the Information section.</p> <p>Note: An overhaul repair is recommended.</p>

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Information

Use the document below to help aid in comparison.

Labor Rate

Labor Cost 0.00

OLH Cost 0.00

Total Repair Cost 0.00

Components required to Replace > \$150 (Warranty Cost + Warranty Markup)

<u>Part#</u>	Part Name	Part Cost
--------------	-----------	-----------

Total Parts over \$150.00 for Replace 0.00

Summarized Parts Less Than \$150.00 for Replace

Total Parts Cost For Replace 0.00

Labor Op Code for Replace

Labor Hours for Replace

OLH for Replace

Labor Rate

Labor Cost for Replace 0.00

OLH Cost for Replace 0.00

Total Labor for Replace 0.00

Total Repair Cost \$ 0.00

Total Replace Cost	\$ 0.00				
--------------------	---------	--	--	--	--

Take pictures of the damaged components.

Note: Transfer case is serviceable, unless it is determined the case halves are damaged.

Special tools are available through the GM tool loaner program to complete the necessary Transfer case repairs

PIP5894: Diagnostic Aids for Transfer Case Actuator Alignment

GM transfer case training 90322.10V

Please contact your GM M/D Service Operations Manager with any labor operation questions

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8421162	Transfer Case Overhaul	Straight Time

Version	1
Modified	Released March 24, 2023

