



Technical Journal

TITLE:

12V battery drained with High Voltage charge cable connected

REF NO: TJ 31582.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2018-01-26	STATUS DATE: 2018-02-01
FUNC GROUP: 3111	FUNC DESC: Battery, complete	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
2XX	BC						2017-2018		-	201617-201747
2XX	BR						2018-2018		-	201726-201747

CSC Customer Symptom Codes

Code	Description
LM	Battery/Dead battery
LN	Battery/Weak or low electrical power

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

*Structure week range updated.

If the customer complains of no start, and the 12V battery is drained after the High Voltage charge cable has been connected for 5 days or more, please see instruction under service.

SERVICE:

Please perform a software update according to TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3111.