



Subject		Market
MIL ON and Multiple DTC for MGR Communication Codes		USA
Service Category	Section	
Drivetrain	Hybrid Transmission/Transaxle	
Applicability		
23MY RX500h AWD		

APPLICABLE VEHICLES

2023	RX500H
------	--------

CONDITION

Vehicle may exhibit one or all in combination of the following DTC U115687 or U11B900 or U11B987 or U11BF87 shortly after short pin installed during PDS/PDI.

RECOMMENDATIONS

If you have cleared the codes and the codes have returned with the vehicle odometer over 13 miles and has over 12hrs since short pin installed, please contact TAS. Please create a TAS case and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references