



Account Team Coverage

ATC Number: atc2685	Revision:	Released Date: 20-Apr-2023
ISX12N CM2380 X120B Fuel Shutoff Valve Upfit ATC for Amazon		Expiration Date (U.S. and Canada): 20-Oct-2024
		Expiration Date (International): 20-Oct-2024

Attention

- U.S. / Canadian Dealers
- U.S. / Canadian Distr./Branches and Div. Offices (Automotive)

If additional information is required, please contact your Cummins Warranty Operations Group Leader.

Description

This ATC is being issued to address potential fuel shutoff valve failures on certain ISX12N CM2380 X120B engines. This document authorizes Cummins certified locations to replace fuel shutoff valve part number 5537854 or 5467826 with an improved fuel shutoff valve.

Note : This document authorizes proactive repairs. All failures will need to be filed to the appropriate coverage.

Action

In order to qualify for repair under this field action, an engine:

1. will be covered Regardless of coverage status, and
2. **must** show as OPEN on QuickServe® Online for this field action.

Note : The ESN list is attached for reference.

After verifying that the engine meets the above requirements, perform the following actions:

1. Remove and Install the fuel shutoff valve. Please refer procedure 019-050 Fuel Shutoff Valve in the appropriate Service Manual.

Material Disposition

Materials removed as a result of this field action **must** be scrapped.

Reimbursements

Parts

The following parts are covered under this field action:

Part Number	Quantity	Description
571296800	1	VLV,SHO

Note : SRTs to gain access that are required to complete the repair, that are sufficiently explained in the claim narrative, may also be claimed on this action.

Labor Using Applicable Access Code and Time

SRT Code	Description	Time (hrs)
00-90X	Administrative time	
19-0VR	Fuel Shutoff Valve - Remove and Install - ISX12N CM2380 X120B	

Travel

Travel is **not** covered under this field action. Towing is **not** covered under this field action.

Other Claimables

Consumables are **not** covered under this field action.

Claim Instructions

For Cummins Dealers, claims for this Field Campaign **must** be filed via **RAPIDSERVE™** Web (rsw.cummins.com). For information regarding **RAPIDSERVE™** Web, please reference the "Warranty" tab in QuickServe® Online. If there are additional questions, please contact your local Cummins Distributor.

Claim Codes	
Description	Code
Account Code:	27
Pay Code:	North America Distributor = X
Pay Code:	North America Dealer = D

Claim Codes

Description	Code
Pay Code:	International Distributor = I
Pay Code:	International Dealer = R
Failure Code:	WNRFSB

Attachments

Click here to see atc2685_esn-list.xlsx

(/service/english/attachments/atc2685_esn-list.xlsx)

Engine Family	Fuel System
Design Application	Market Application
All	All

Document History

Date	Details
	Document Created; 20-Apr-2023

Last Modified: 20-Apr-2023
