



SIB 63 01 22 INFO - K5X LED HEADLIGHT

2023-04-24

This Service Information Bulletin replaces SIB 63 01 22 **dated Nov 28, 2022**.

What's New (Specific text highlighted):

- Euro spec switch included in the kit

MODEL

Model	Model Description
K50/12	R 1250 GS
K51/11	R 1250 GS Adventure

The affected vehicles have been marked with campaign number **INFO202208** in AIR.

In order to determine if a specific vehicle is affected by this campaign, it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

LED headlights were temporarily unavailable from the Factory and some R 1250 GS and R 1250 GS Adventure units were built with the halogen headlight in order to ensure safe use.

CORRECTION

The Monroney Label was updated, and pricing was adjusted to reflect the change from LED to halogen headlight prior to any wholesale and retail of any motorcycle.

A later LED headlight retrofit to replace the halogen headlight will be offered for vehicles that are equipped with options (Dynamic ESA (SA 0191) and factory installed cruise control (SA 0538)).

NOTICE

At present, the LED headlight retrofit is not possible as not all the required part/s are available. A delivery date will be communicated once there is more information about availability, including the retrofit part number/s and pricing.

PARTS INFORMATION

Part Number

77 51 1 542 186	Kit LED-Headlight	QTY: 1
-----------------	-------------------	--------

NOTE: The kit includes the (ECE) Euro spec version switch that includes a switch to turn the headlight off. **Do not install** this switch on US spec version motorcycles.

Euro (ECE) Spec switch

Copyright ©2023 MOTORRAD USA, a division of BMW of North America, LLC. All Rights Reserved



QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 63 01 22 INFO - K5X LED Headlights.pdf](#)

Service Information Bulletin

Lights

April 24, 2023

63 01 22

INFO - K5X ADAPTIVE LED HEADLIGHT



**BMW
MOTORRAD**

This Service Information Bulletin replaces SIB 63 01 22 dated Nov 28, 2022.

What's New (Specific text highlighted):

- Euro spec switch included in the kit

MODEL

Model	Model Description
K50/12	R 1250 GS
K51/11	R 1250 GS Adventure

The affected vehicles have been marked with campaign number **INFO202208** in AIR.

In order to determine if a specific vehicle is affected by this campaign, it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

LED headlights were temporarily unavailable from the Factory and some R 1250 GS and R 1250 GS Adventure units were built with the halogen headlight in order to ensure safe use.

CORRECTION

The Monroney Label was updated, and pricing was adjusted to reflect the change from LED to halogen headlight prior to any wholesale and retail of any motorcycle.

A later LED headlight retrofit kit will only be offered for these R 1250 GS and GS Adventures with option code (019Z). If a customer requests this retrofit, double check the option code using AIR.

NOTICE

At present, the LED headlight retrofit is not possible as not all the required part/s are available. A delivery date will be communicated once there is more information about availability, including the retrofit part number/s and pricing.

PROCEDURE

If the customer decides on having the Adaptive LED Headlight retrofit kit and their motorcycle has the required option code (019Z), it can be purchased and installed at the customer's expense.

PARTS INFORMATION

Part Number

77 51 1 542 186	Kit LED-Headlight	QTY: 1
-----------------	-------------------	--------

NOTE: The kit includes the (ECE) Euro spec version switch that includes a switch to turn the headlight off. **Do not install** this switch on US spec version motorcycles.

Euro (ECE) Spec switch



QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department