



Bulletin No.: PIT6009
Published date: N/A

Preliminary Information

PIT6009 Front License Plate Bracket Missing at PDI

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer	2023	1/30/2023	4/19/2023	All	All

Involved Region or Country	North America
Additional Options (RPO)	VK3
Condition	It may be discovered when performing the PDI on a vehicle that the front license plate bracket is not included with the loose items. If the vehicle was delivered to a state that requires a front license plate or has option code VK3 it should be included.
Cause	Plant packaging error. This is NOT a transportation issue.

Correction:

Order license plate bracket part # 42708218.

You may need to place a SPAC case on the order.

Parts Information

Description	Part Number	Quantity
License Plate Bracket	42708218	1

Version History

Version	1
Modified	5/02/2023 - Created.



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.