

REFERENCE:	Nova Bus Manuals
SECTION:	16: Electrical System
RS N°:	MQR 7621-2397
EFFECTIVE IN PROD.:	N/A

APPLICATION DEADLINES: 2024JL31
CLAIM REFERENCE NUMBER: WB5437

SUBJECT:	VBEA Program - Ramp Lift-U
JUSTIFICATION:	The supplier Lift-U recommends the addition of a detection delay to prevent wrong fault code in the AVM.

LEVEL	DESCRIPTION	DIRECT CHARGES		TIME
		LABOUR	MATERIAL	
1	Modify VBEA programming to add a fault detection delay.	Nova Bus	–	20 min
2	–	–	–	–

MATERIAL REQUIRED PER VEHICLE

QTY	PART N°	REV.	DESCRIPTION
LEVEL 1			
1	–	–	–
LEVEL 2			
–	–	–	–

DISPOSAL OF PARTS

REMOVED PARTS ARE:	DISCARDED	RETAINED	–
	–	–	

REVISION HISTORY

REV.	DATE	CHANGE DESCRIPTION	WRITTEN BY
NR	2023JN15	Initial release	Annie St-Jacques

APPROVED BY:

Irina

Negoescu

Signature
numérique de Irina
Negoescu
Date : 2023.06.15
10:54:04 -04'00'

PAGE 1 OF 2

NQF772004 VERSION 3

* Please contact your customer support manager to obtain the version of the software update

CLIENT	ORDER	ROAD NUMBER		VIN (2NVY/4RKY...)		QTY	PROGRAM	REV.
		FROM	TO	FROM	TO			
New York City Transit New York - NYCT	LC79	9623	9784	L82L1M9777782	L82L4M9777954	162	FB_NYC4HE_M_02	R
New York City Transit New York - NYCT	LD06	8755	8758	L82J3L9777778	L82J3L9777781	4	FB_NYC4DE_M_05	H
New York City Transit New York - NYCT	LD08	8759	8931	L82J5M9778156	L82J8N9778508	205	FB_NYC4DE_M_05	H
New York City Transit New York - NYCT	LD23	9620	9622	L82LXL9777634	L82L5L9777668	3	FB_NYC4HE_M_02	R
New York City Transit New York - NYCT	LD64	9785	9910	L82L0M9777871	L82L1M9778155	126	FB_NYC4HE_M_03	K