

**Tech Tip** T-TT-0735-23

May 10, 2023

**Mongoose MFC3 Cable - Door Panel Interference** 

USA

Power Source/Network

Networking


2022-2023 GR86

### **APPLICABLE VEHICLES**

2022-2024 86

## **CONDITION**

When using a Mongoose MFC3 cable to connect for diagnostics to the DLC connector on current generation GR86, the cable may contact the driver's door panel when closed. Please see attached photos for an example of this condition. It is recommended that an ADVi unit be used for diagnostics or the driver's door remain open if using a Mongoose MFC3, to prevent any damage to the DLC connector, cable, or door panel.



#### **RECOMMENDATIONS**

Please utilize the ADVi unit for diagnostic work or leave the driver's door open when using the Mongoose MFC3 on all 22-23MY GR86 vehicles.

## **LINK REFERENCES**

This Tech Tip does not contain any link references

Expires on 05/10/2024

© 2023, Toyota Motor Sales, USA

Page 1 of 2



# **Tech Tip** T-TT-0735-23

May 10, 2023

Mongoose MFC3 Cable - Door Panel Interference

USA

05/10/2024 Expires on

Ver. 5.0 01/01/2023 T