

Rear Spoiler Sporadically Inoperable with Fault Message in Instrument Cluster

Topic number	LI77.25-P-076544
Version	1
Function group	77.25 - Wind deflector (spoiler)
Date	6/8/23
Validity	All vehicles of model series 232 with software A 000 902 16 90 on control unit N145/1 AMG Drive Unit and up to and including manufacturing date May 31, 2023.
Reason for change	

Complaint

Rear spoiler sporadically remains in opened or closed position and a fault message appears in the instrument cluster. The rear spoiler can then no longer be actuated manually using the button.

The function of the rear spoiler is re-established after an ignition reset and the fault message is no longer present in the instrument cluster.

Cause

Software of the AMG DRIVE UNIT.

Remedy

Remedy valid for all vehicles of model series 232 with software A 000 902 16 90 on control unit N145/1 AMG Drive Unit and up to and including manufacturing date May 31, 2023

--> Perform software update of the AMG DRIVE UNIT N145/1 to Latest SW Available.

Symptoms				
Body > Body/Cab > Spoiler > Does not move in/out				
Control unit/fault code				
Control unit		Fault text		
N145/1 - AMG DRIVE UNIT (AMG DRVU) (DRVU3)				
Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note