

Tech Tips

TT 55-13-01

Date: July 12, 2013

2001-2006 Jetta Wagon, 2004-2008 Touareg (without Rear View Camera) – Rear Lid Does Not Open After Handle Replacement

If the rear lid handle is replaced with part number 1J0 827 566L, the microswitch from the original handle must be transferred to the new handle. If original microswitch is not available, microswitch part number 1J5 962 104 B should be ordered and installed.



To remove micro switch, gently pry it away from handle.



To install micro switch, align mounting tabs with handle alignment holes.