

Uncontrolled Copy

ID # CBR-2112

Version 4

Title

Programming Failure - Chassis With Cummins Engine And An Allison Transmission

Abstract

It has been found that some units with a Cummins engine and an Allison transmission may be able to read parameters but unable to program multiple OEM modules.

Content

It has been found that some units with a Cummins engine and an Allison transmission may be able to read parameters but unable to program parameters.

Advise to follow this procedure :

1. Remove the fuse for the Allison transmission.
2. While disconnected from the truck, finish work in PTT and remove this vehicle from the " Latest Selections " list.
3. Connect to the truck's 16 pin diagnostic connector and read the vehicle data (minus the Allison and Cummins). Parameter programming should now function properly for chassis related programming with the Allison disconnected.
4. Reconnect the fuse and read/clear DTC's.

Tags

cummins allison parameter programming

Categories

Vehicle System > Control Systems