

Uncontrolled Copy

ID # CBR-2297

Version 1

Title

Volvo Chassis - Nonfunctioning 12v Accessory Power Supply - Model Year (MY) 2017 To Present

Abstract

It may be possible for some MY 2017 and newer Volvo trucks to have a nonfunctioning under-bunk 12v accessory power supply due to a blown F80 fuse.

Content

It may be possible for some MY 2017 to present Volvo trucks to have a nonfunctioning under-bunk 12v accessory power supply due to a blown F80 fuse.

If you have a nonfunctioning underbunk 12v accessory power supply and fuse F80 is blown please inspect the under-bunk connector as seen in the images below.



This connector should not be connected together. These connectors are not used.

Male connector wire ID	FA107#1318
Female connector wire ID	F80A5#2019B
	FA111#1304

Live UI ct the connector, replace fuse 80, and verify the repair.

Tags

volvo

12v outlet

fuse

Categories

Make and Model > Volvo > VNL

Make and Model > Volvo > VNR

Make and Model > Volvo > VNX

Make and Model > Volvo > VAH

Make and Model > Volvo > VHD

Vehicle System > Electrical