

# Uncontrolled Copy

[Print](#)

**ID #** CBR-2301

**Version** 2

---

## Title

Volvo Chassis - Instrument Cluster (IC) Immobilizer Pass Code Not Working

## Abstract

Trucks produced between March 27, 2023 and September 16, 2023 that have the IMMOB variant are not able to change the 3 digit code to customize the pass code. This feature will only work when the pass code is 000.

## Content

Published July 26,2023

## Valid For

VNL, VNR, VAH vehicles built between March 27, 2023 and September 16, 2023.

Trucks produced between March 27, 2023 and September 16, 2023 that have the IMMOB variant are not able to change the 3 digit code to customize the pass code. This feature will only work when the pass code is 000.

## Repair

Update the (IC) software with PTT to the latest version. Ensure the APCI file is updated on PTT.

## Tags

volvo

password

pass code

## Categories

Make and Model > Volvo > VNL

---

Make and Model > Volvo > VNR

---

Make and Model > Volvo > VAH

---

Vehicle System > Instrumentation

---

Vehicle System > Control Systems