



Tips and Tricks Revision 10

Date: July 31, 2023
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 10. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 10 New Additions		
#	Subject	Model Affected
1	Publication CR253: Replacement of water radiator electric fan motors, BBS fuse replacement and BBS software update	DIAVEL
2	New part number for the brake fluid reservoir bracket	PANIGALE
5	Possible poor sealing of the water pump gear oil seal	ALL MODELS
6	Information on modifying the tightening torque of the foot peg holder plate and stand support fixing screws	ALL MODELS

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.