

APB1 Stop Delivery - Re-programming gateway control unit

APB1 Stop Delivery - Re-programming gateway control unit

ID Number	APB1
Models	Cayenne (9YA/9YB)
Model Years	2024
Number of VINs Affected	1,913
VIN List	Attached
Issue Description	Due to an issue with the hazard warning lights, affected vehicles are on Stop Delivery until further notice.
What should Dealers do?	Please do not deliver the subject Stop Delivery vehicles until the remedy is complete.
What will Porsche do?	Vehicles will have the remedy performed once it is available.
TI Number	To be released at a later date.
Customer letter	To be posted at a later date.
Customer Reactive Statement	TBD.

Important information

IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Attachments

- [1. VIN_List_Report_APB1_2023-07-28_V2 Stop Delivery only.xlsx](#)