WPG4 Workshop campaign - Replacing rear wing circlips

WPG4 Workshop campaign - Replacing rear wing circlips

ID Number WPG4			
Models 911		911 GT3 RS (992)	
Model Years		2023	
VIN List		Attached	
Number of affected VINs		12	
Issue Description		On the affected vehicles, it rings for fixing the bearing ve not been fitted in accord ons.	bolts of the rear spoiler ha-
		If this is the case, the beari not sufficiently secured axia and can move out of the be vehicle.	
		As a result, noticeable vibra area of the vehicle during c	
		For this reason, the retainir	ng rings must be replaced.
What should Dealers do?		Please arrange for this measure to be carried out as soon as possible on affected vehicles.	
		The remedy is now availa	ble as of 7/28/23.
		Parts can be ordered via PPL as normal.	
TI Number		No. 73-23	
Customer Notification		To be posted at a later date.	
Required par	rts		
Part number	Designation	Quantity/vehicle	Parts return*
9GT898533	Circlip repair kit	1 set (contains 14 circlips)	No

*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

Warranty processing

Validity:

This workshop campaign will be carried out up to May 17th, 2028 and will be closed on that date. Please note that warranty claims can only be processed up to this date.

Scope 1:	
Damage Code	WPG4 66 000
Repair Code	2
Labor time	78 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be ensured by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the campaign scope.

Attachments

1. VIN_List_Report_WPG4_2023-07-28_V2.xlsx