

## Rear Spoiler Sporadically Inoperable with Fault Message in Instrument Cluster

---

Topic number	LI77.25-P-076544
Version	2
Function group	77.25 - Wind deflector (spoiler)
Date	8/18/23
Validity	Model series 232 - For production date details, see remedy
Reason for change	Validity and remedy adapted (country variants and coding)

---

### Complaint

Rear spoiler sporadically remains in opened or closed position and a fault message appears in the instrument cluster. The rear spoiler can then no longer be actuated manually using the button.

The function of the rear spoiler is re-established after an ignition reset and the fault message is no longer present in the instrument cluster.

### Cause

Software of the AMG DRIVE UNIT.

### Remedy

All vehicles of model series 232 with M177 (SL55/63) from start of production - end of modification year 22/1 - manufacturing date before April 21, 2023:

--> Perform software update of the AMG DRIVE UNIT N145/1 to Latest SW Available.

All vehicles of model series 232 with M177 (SL55/63) from start of modification year 22/2 - manufacturing date on/after April 21, 2023:

--> Perform SCN coding of the AMG DRIVE UNIT N145/1.

Valid for all vehicles of model series 232 with M139L (SL43) from start of modification year 22/1 - manufacturing date on/after April 21, 2023:

--> Perform SCN coding of the AMG DRIVE UNIT N145/1.

<b>Symptoms</b>
Body > Body/Cab > Spoiler > Does not move in/out
<b>Control unit/fault code</b>

# XENTRY TIPS

---

Control unit	Fault text
N145/1 - AMG DRIVE UNIT (AMG DRVU) (DRVU3)	

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note