



Tips and Tricks Revision 12

Date: August 8, 2023
To: Dealer Principal, General Manager, Service Manager, North American Dealer Network
From: Richard Kenton, Technical Director
Dan Schwartz, Service Area Manager

Dear Dealers,

This bulletin is to notify you of important updates included with the recent release of Tips and Tricks Revision 12. A brief summary of each new addition is listed below, but please review the complete document hosted on DCS for further details. [Ducati - Bulletins](#)

Revision 12 New Additions		
#	Subject	Model Affected
1	Various DTC, DWC, DQS, BSD, Cruise Control warning lights illuminating	MULTISTRADA
2	Surface damage of oil sump	STREETFIGHTER
3	New upper chain sliding shoe and adhesive neoprene pad	STREETFIGHTER
4	New engine ECU calibration for DP1 exhaust system	ALL MODELS

This bulletin is only applicable for Ducati Motorcycles manufactured and configured for the Ducati North American market (USA, Canada and MX).

For questions about this Service Bulletin,
please contact your Service Area Manager.