

## **SSM 51885 2020 Aviator - Center Display Screen Will Not Shift To Night Mode Or Lines On Center Display Screen With Multi Color Or Rainbow Hue**

---

Some 2020 Aviator vehicles may exhibit a concern where the center display screen will not shift to night mode or has lines on the center display screen with multi color or rainbow hue. This may be due to SYNC module (APIM) software. To correct the condition, run the APIM-SYNC Module (APIM) Standard Programming application using the latest software level of the Ford Diagnosis and Repair System (FDRS). For claiming, use causal part 14G371 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.