

Reference	SSM76012
Models	New Range Rover / L460 New Range Rover Sport / L461
Title	Vehicle Interior Trim Damage Noted At Pre Delivery Inspection (PDI)
Category	Body
Last modified	04-Aug-2023 00:00:00
Symptom	107000 Interior Trim

Content **Model / Model Year / Derivative**
 Range Rover / 23MY Onwards
 Range Rover Sport / 23MY Onwards

Situation:

JLR Engineering are investigating reports of interior trim damage noted at Pre-Delivery Inspection (PDI) or earlier in the supply chain.

Action:

Follow the instruction below.

Service Instruction:

If interior trim damage is identified at PDI or earlier, submit an electronic Product Quality Report (ePQR) with photographs of the trim part(s) affected and description of the repair(s) completed to rectify the concern.

(000362530)

anBhdHRicnM7MjAyMy0wOS0wQFQxMzo1Nz00N4yMDNaOzEzNi4yMjYyNzQuMTEzOw==