

**Subject: Engineering Information - Failed or Thrown Accessory Drive Belt**

*This PI has been revised to end the need for gathering information from the field. Please discard PIE0750.*

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2023	2024	—	—	Equipped with 1.2L (RPO LIH)	—
Chevrolet	Trailblazer (VIN M)						
	Trax	2024					

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released May 19, 2023 Revised August 16, 2023 - Ended the need for gathering further information from the field.