

Technical Service Bulletin

93 U153D00 battery serial number China

93 23 27 2071344/1 September 13, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5 e quattro	2020 - 2022	All	Not Applicable

Condition

Customer States:

• There is no customer complaint; this concern is found during diagnosis.

Workshop findings:

• The label of the HV battery is damaged or missing, and the serial number of the battery cannot be read.

OR

Although the label of the HV battery does not show a serial number for China, the following DTC and symptom code combination is stored in the Control Module for Hybrid Battery Management, -J840- (address word 008C):

• U153D00 Battery serial number China

Technical Background

This is a diagnostic issue.

Production Solution

Not applicable.

Service

Please enter any number with 24 or 26 digits if the GFF requires that you enter a serial number and one of the following applies:

- The DTC Code U153D00 is stored in the Control Module for Hybrid Battery Management.
- The HV Battery label is damaged or missing.
- The serial number on the label does not have 24 or 26 digits.

Warranty

© 2023 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2071344**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.