

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.

# VW Elsa Newsletter



Das Auto.

Edition 60: November 4, 2013

## Content

- [ODIS Quick Reference Guide](#)
- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Tech Tips](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



## ODIS Quick Reference Guide

Several weeks ago, the ODIS Quick Reference Guide was sent to all dealer technicians (non-corporate users) to assist them in navigating through key ODIS information. For easy access, we are including a link to the document.

Please go to: [www.vwclub.com/snetljct/en/web/vw/offboard-diagnostic-information-system-odis](http://www.vwclub.com/snetljct/en/web/vw/offboard-diagnostic-information-system-odis) to download the ODIS Quick Reference Guide.

[Back to top](#)

## Technical Bulletins

**01 13 35 - 2028609 Supersedes T.B. V011236 dated December 18, 2012 to update SVM applicability table.**

**Update Programming for Engine Control Module and Transmission Control Module, for Shudder and/or Slight Hesitation Concerns**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta SportWagen, Golf, Jetta Sedan, Beetle Convertible, Passat	2012–2013	2.0L (CJAA)	6 spd. DSG (02E)	All	All

Current ECM/TCM programming could be causing slight hesitation related concerns in DSG equipped vehicles (depending on driving conditions).

**Production Solution:** Improved ECM/TCM software to address drivability concerns and slight hesitation complaints.

**44 13 05 - 2031087 Supersedes T.B. V441304 dated June 27, 2013 to add model year 2014 and to remove model year 2012 along with models Jetta, Jetta Hybrid, Beetle Sedan and Beetle Convertible applicability.**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2013–2014	All	All	All	All

### Four Wheel Alignment and Vehicle Drift-Pull Overview

This Technical Bulletin provides an overview for performing vehicle four Wheel Alignment, and information on improving vehicle drift/pull using selective tire placement. The information provided is based on the Hunter alignment equipment, Hunter GSP9700 with StraightTrak® (VAS 6230x ) and John Bean RFV2000 with OptiLine (VAS 6311A) diagnostic balancer. The alignment information provided in this bulletin is not limited to the Hunter alignment equipment, and still applies with the use of other Volkswagen approved alignment equipment. The diagnostic procedure for selective tire placement, to improve vehicle drift/pull, will require the use of one of the diagnostic balancers previously mentioned.

**Production Solution:** Extensive analysis was conducted by Volkswagen for concerns of vehicle drift/pull and it has been determined that this condition is NOT caused by any production issues with the vehicle's steering or suspension systems. The main contributors for these concerns are tire pull and road surface tilt (road crown). Tire

pull is a natural condition of radial tire construction and road surfaces are tilted for water drainage. The intent of the information provided in this bulletin is to optimize the straight ahead tracking of the vehicle for customer satisfaction.

**87 13 01 - 2005566 Supersedes Technical Bulletin V871204 dated April 26, 2012 to update Passat vendor code in the warranty table.**

**HVAC, Unpleasant Odor**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (except Routan)	2000–2013	All	All	All	All

Unpleasant odor is coming from Heating and Ventilation system. Odor mainly occurs after vehicle has been sitting (unused) at least 5 hours and within 20 to 60 seconds after vehicle is first started.

**Production Solution:** Not applicable.

## Pending Service Solutions

No new pending service solutions this week.

[Back to top](#)

## Tech Tips

**20-13-03TT - In-Tank Fuel Pump Pressure Specified Value  
November 1, 2013: Update to Information.**

Model(s)	Year	Eng. Code	Trans. Code
Tiguan	2009–2013	All	All

Be aware that the specified value for pressure from the in-tank (low side) fuel pump is 2.7 bar or higher.

**91-12-08TT - Bluetooth Compatibility  
November 1, 2013 – Update to Information.**

Model(s)	Year	Eng. Code	Trans. Code
Routan	2010–2013	All	All

CC, EOS, Golf, GTI, Tiguan, Jetta, Jetta Sportwagen, Touareg	2011–2012	All	All
Passat, Beetle	2012–2013	All	All
<p>To check Bluetooth compatibility for all 2011 and newer vehicles, as well as 2010 Routan, use the link below.</p> <p>The web address can also be provided to customers. <a href="http://www.vw/bluetooth.com">www.vw/bluetooth.com</a></p>			

[Back to top](#)

## Campaigns

No new campaigns this week

[Back to top](#)

## Updates

No new updates this week.

## Suggestions

Please send comments or suggestions to: [ywoa.workshopinformation@vw.com](mailto:ywoa.workshopinformation@vw.com)

[Back to top](#)

© 2013 Volkswagen of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.