

Volvo Chassis - Nonfunctioning 12v Accessory Power Supply - Model Year (MY) 2017 To Present

Published Date: 9/12/2023


Valid For:

Models - VNL,VNR,VNX,VAH,VHD

Model Years - 2017 to Current

It may be possible for some MY 2017 to present Volvo trucks to have a nonfunctioning under-bunk 12v accessory power supply due to a blown F07 fuse.

If you have a nonfunctioning underbunk 12v accessory power supply and fuse F07 is blown please inspect the under-bunk connector as seen in the images below.



This connector should not be connected together. These connectors are not used.

Male connector wire ID	FA107#1318
Female connector wire ID	F80A5#2019B
	FA111#1304

Disconnect the connector, replace fuse 80, and verify the repair.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article