

WPJ6 Workshop campaign - Re-code loudspeaker amplifier (Bose)

WPJ6 Workshop campaign - Re-code loudspeaker amplifier (Bose)

ID Number	WPJ6
Models	911 (992) Macan (95B)
Model Years	2019 - 2023
VIN List	Attached
Number of affected VINs	90,439
Issue Description	<p>On the affected vehicles, there is the possibility that scratching and booming noises may occur at maximum output of the woofer in combination with increased bass settings.</p> <p>In order to prevent this, the control unit of the loudspeaker amplifier (Bose) must be re-coded on the affected vehicles.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (9/8/23) the remedy is now available.</p>
TI Number	No. 102-23

Attachments

- [1. VIN_List_Report_WPJ6_2023-09-08.xlsx](#)